



Service bulletin

164 Aime Vincent, Vaudreuil, Qc, Canada, J7V 5V5
Phone: (450) 424-8150, Fax: (450) 424-9262
website: rftel.com e-mail: info@rftel.com

Bulletin # 2007

Date: June 20, 1999

Part affected: Controller board 229-47-329, Interface board 229-47-339

Products affected RT9000

At issue: Compatibility

Controller board Rev. 7B and higher

Rev. 7B and higher versions of the controller board have an upgraded radio interface board. A Rev.7B or higher board should not be replaced with a lower revision unless upgraded to Rev. 7B.

Controller board Rev. 7 and lower

Rev. 7 and lower versions of the controller board have a non-upgraded interface board. A Rev. 7 and lower board should not be replaced with a higher revision unless the interface board is upgraded. An upgraded interface board can be recognized by a surface mount capacitor standing on edge between C12 and C13.

picture